

Project Information							
Date:		Pinchin Repres	sentative:	Report Number: 01			
August	24, 2023	Dzuy Dang		Pinchin File: 331135.000			
Project	Name:		Site Address:				
Mould	and Water Damage Rem	nediation	Milton Courthouse, 491 Steeles Avenue East, Milton, Ontario				
Client: Client File Number:							
CBRE N/A							
Contra	ctor:	Arrival on Site: 6:00 PM					
Gardin	er Environmental Service	Number of Workers: 1					
Distribution:							
CC:	Faye Greaves	CBRE	E <u>fa</u>	ye.greaves@cbre.com			
	Eric Manzano	CBRE	<u>e</u>	ric.manzano@cbre.com			
	Cheryl Britt	Pinch	in <u>cl</u>	<u>pritt@pinchin.com</u>			

Description of Work in Progress

Material	Work Area	Work in Progress	Type of Review	Status
Mould	Work Area 1: Courtroom 1 (Room 384) and Courtroom 2 (Room 383)	Canadian Construction Association (CCA) Level 1 mould procedures	Visual Clearance	Acceptable


Discussion	One mould-impacted ceiling tile from Courtroom 1 and two water-stained ceiling tiles from Courtroom 2 have been removed and replaced.
Action Items	Note that the contractor did not remove all water stained ceiling tiles as they reported to Pinchin that they were directed to only remove 2 and they did not have enough replacement tiles.

Observations - Work Area 1: Courtroom 1 (Room 384) and Courtroom 2 (Room 383)

Site Isolation & Facilities/Equipment	Acceptable	A Level 1 work area was created by laying a drop sheet below the work area. All necessary tools on site were observed to be in good and working condition.
Cleaning	Acceptable	HEPA vacuum (D.O.P. tested August 1, 2023) was used to clean up any debris caused by the removal of the ceiling tiles.
Waste Handling	Acceptable	No waste materials remain in the work area.
Other	Acceptable	One mould-impacted and two water-stained ceiling tiles identified within Courtroom 1 and Courtroom 2 has been removed.



Observations - Work Area 1: Courtroom 1 (Room 384) and Courtroom 2 (Room 383)



Map showing affected ceiling tiles removed (Green Mould Impacted and Blue Water-stained).



View of Courtroom 2 after abatement of water-stained ceiling tiles.



General view of work area in Courtroom 2.



View of Courtroom 1 after abatement of mould-impacted ceiling tile.

\pinchin.com\Miss\Job\331000s\0331135.000 CBRE,IO,491SteelesE,Milton,IEQ,MIAQ\Deliverables\Site Review\331135 Site Review 01, FIr 3, MCH, 491SteelesE,Milton, CBRE, August 24, 2023.docx Template: Site Review Report Template HAZ, June 30, 2021